


-: TRANSFORMER :-

Features: \rightarrow Which transfer power from one ckt to another ckt without changing frequency.



1. Constant frequency device.
2. A constant power device.
3. An electromagnetic energy conversion device. (Intera collect)
Electrical energy convert to magnetic energy & stored in magnetic field & re convert to electrical energy.
4. Overall transformer \rightarrow Not an energy conversion device.
5. Transformer is a coupled ckt. (Electrically isolated)
6. Transformer can be treated as phase shifting device same as transducer in electronics ckt. It gives 180° phase shift to it's input signal.
7. Single Excited device.
8. Transformer is a control ckt (or) -ve feedback ckt.
9. Transformer is a constant flux device.
10. Transformer is a two port N/W. O/P & I/P quantity can be related by A, B, C, D parameter.

WORKING PRINCIPLE :-

Faraday's law of electromagnetic induction :-

When there is a ^{relative} space variation or time variation b/w a magnetic field & a set of conductor, an emf is induced in set of conductor.

Basic requirement :-

1. Magnetic field

2. Set of conductor

3. Relative space variation or ^{relative} time variation.

Method - 1 - Relative space variation. (Dynamically or motionally induced emf.)

Magnetic field \rightarrow Steady or time invariant. Ex: DC Gen

Set of conductor \rightarrow being moved in mag field.

Hence there is a space variation b/w mag field & conductor.

Method - 2 Relative time variation (Statically induced emf)
(b/w \rightarrow conductor is constant)

Mag field \rightarrow Time varying (A.C supply)

Conductors \rightarrow Stationary.

Ex \rightarrow Transformer.

Dynamically induced emf :-

① This is emf induced in set of conductors which are being moved inside a time invariant mag field. The rate

is dynamically or motionally induced emf


Statically induced emf :-

① This is emf induced in ~~the~~ set of stationary conductor which are placed in time varying magnetic field.

② The nature of emf in transformer is statically induced emf.

Dynamically induced emf.

flux cutting rule.




$$E_d = BLV \sin \theta$$

B - flux density in Tesla

L - effective length / active length of conductor in m

v → velocity of moving conductor - m/s

θ → angle betⁿ B & v in degree.



$$dE_d = B V \sin \theta dl$$

$$E_d = \int_{\text{line}} B \cdot V \sin \theta dl$$

limits active length.

$$E_d = \int_{\text{line}} (\vec{V} \times \vec{B}) dl$$


$$\text{Not } \int_{\text{line}} (B \times v) dl$$

Right hand
rule

can be find out

→ this will give ~~wrong~~
direction of induced
emf

* Direction of dynamically induced emf is perpendicular to the plane containing the velocity & flux density vector.




According to Fleming's R.H.L the induced emf direction is always \perp to the plane containing velocity & flux density vector.

Magnitude of statically induced emf.

1. Faradays second law,

$$E_s = \text{Rate of change flux linkage.}$$



$$i = I_m \sin \omega t$$

$$\text{MMF} = Ni$$

$$= NI_m \sin \omega t \quad (\text{alternating in nature})$$

$$\text{flux} = \frac{\text{mmf}}{\text{Reluctance}} \quad (\text{A flux produced in core due to alternating mmf})$$

$$\phi = \frac{NI_m \sin \omega t}{R}$$

$$\phi = \phi_m \sin \omega t \quad \text{flux linkage} = N\phi \quad (\text{The flux is also alternating})$$

$$= N\phi_m \sin \omega t$$

$$E_s = \frac{d(N\phi)}{dt}$$

$$E_s = -N \frac{d\phi}{dt} \quad \left[\text{To satisfy lenz's law the -ve sign is given.} \right]$$


Here two laws are involved.

1. $N \frac{d\phi}{dt} \rightarrow$ Faradays 2nd Law

2. (-) \rightarrow lenz's law.

Generalized representation of statically induced emf.


Flux line \perp surface & indel \perp normal.



(i)


$$\phi = BA$$

Flux inclined to surface.



(ii)

$$\phi = B \cos \alpha A$$



$$d\phi = B \cos\alpha \, ds$$

$$\phi = \iint B \cos\alpha \, ds$$

(for) any shape of magnetic ckt (core)

$$\text{So } \mathcal{E}_s = -N \frac{d}{dt} \iint B \cos\alpha \, ds$$

$$= -N \iint \frac{\partial B}{\partial t} \cos\alpha \, ds$$


Flux not only depends on time also depends on other factor, so it is taken partial differentiation, with derivative of other factor w.r.t time is zero.

$$\vec{ds} = ds \cdot \hat{n}$$

$$\text{So } \mathcal{E}_s = -N \iint \frac{\partial \vec{B}}{\partial t} \cdot \vec{ds}$$


Direction of statically induced emf can be found out by Lenz's law.

Lenz's law:-





any time varying quantity having at least two change. (increasing & decreasing)

Circular Conductor



flux due to current flow through conductor.




flux due to ~~current~~ current carrying conductor

According to Lenz's law the direction of statically induced emf such that is such that the current due this emf will flow through a conductor in such a direction which in turn produce some flux according to electromagnetic theory and this flux must oppose the change in main field flux, which is the cause of production of emf as well as current.

Types of statically induced emf:

1. Self induced emf
2. Mutually induced emf



Self induced emf ~~known as~~ statically induced in a coil due to time varying ~~of~~ rate of current through it's own coil.


$$E_{\text{self}} = -N \frac{d\phi}{dt}$$

$$= -\left(N, \frac{d\phi}{di}\right) \frac{di}{dt}$$

$$\text{Self inductance of coil} = L_{\text{self}} = \frac{d}{di}(N\phi)$$

The self inductance ~~of~~ of a coil may be defined as rate of change of flux linkage w.r.t the time varying nature of current flowing through it's own coil.

$$E_{\text{self}} = -L_{\text{self}} \times \frac{di}{dt}$$



$$V_1 = -E_{\text{self}}$$

According to Lenz's law the ^{opposite} self induced emf always ^{the} change in applied voltage, so that there is 180° out of phase with each other in a coupled circuit.

Mutual induced emf is the statically induced emf induced in a coil due to time varying nature of current through another coil which is magnetically coupled to it.

$$e_m = -N_2 \frac{d\phi}{dt}$$

$$= -N_2 \frac{d\phi}{di} \cdot \frac{di}{dt}$$

$$\therefore M = \frac{d(N_2 \phi)}{di}$$


Mutual inductance bet two coil may be defined as the rate of change of flux linkages of a coil with respect to the time varying nature of current through another coil which is magnetically coupled to first one.

$$e_m = -M \frac{di}{dt}$$


Mutual induced emf also opposes the changes in applied voltage source to satisfy the Lenz's law, so that the mutual induced emf and applied voltage is 180° out of phase with one another.

That means in coupled ckt self & mutual induced emf are always in phase with one another.

Types of magnetic coupling :-



If the two coils are said to be tightly coupled if the flux produced by them aids one another in common magnetic ckt.



The two coils are said to be -vely coupled if the flux produced by them opposes one another in the common magnetic ckt.

Dot notation :->


If the current enters or leaves the dots at both the coils then the two coils are said to be +vely coupled and the polarity of mutual inductance betⁿ two coils is +ve.

If the current enter (leaves) dot at one coil leaves (enters) at another coil then the two coils are said to be -vely coupled and the polarity betⁿ of mutual inductance betⁿ them is '-ve'.

The transformer operates on mutual induction principle. This is the main principle of transformer.

Details of Transformer :-

Constructional details of Transformer :-



Transformer core :-

Material construction :- \rightarrow Silicon steel (electrical steel)

feature of silicon steel:

1. Ferro magnetic material.
2. Low reluctance & high permeability to the flow of magnetic flux.
3. Has low hysteresis coefficient.

$$W_h = \alpha \mu^2 f V$$

$\alpha \rightarrow$ hysteresis coefficient.

- 1.6 for silicon steel

- This is the least value compared to other metals.

4. Hysteresis loss is low.

Permeability of steel is reduced by adding silica contained so eddy current reduces & hence eddy current loss will be reduced. [But magnetic property does not change.]

If more silicon is added it becomes brittle. Brittleness will increase for which mechanical strength will reduce.

silicon \rightarrow \downarrow wt \downarrow brittleness \uparrow mechanical strength \downarrow

5. 4% to 5% silica is added to steel.


Eddy current loss can be reduced by decreasing conductivity.

- ① by adding silica to steel
- ② by laminating it's core

6. Crystalline structure.


Shape of crystalline structure \rightarrow Body centered

Body centered cubic.



- Silicon steel ~~offer~~ grain offers high permeability along cube edges when compared along diagonal.


Permeability $\propto \frac{1}{\text{length}}$.



Normal Silicon steel slab
Normal

If the direction of magnetization is in one direction all cubes are not given high μ , so overall μ is low.

As all the grains are in arbitrary position in normal silicon steel so we prefer core steel.




Cold rolling grain orientation process.

after this process all cube are align in one direction, so μ is increase

This steel is called C.R.G.O steel.

For silicon steel grain, higher permeability along the cube edge rather than diagonal. If the cubes are given orientation such that cube edges are parallel to direction of magnetization, the μ of silicon steel further increases. This can be practically achieved by using cold rolling grain orientation process & the resulting steel is called CRGO steel, which is used as core material in modern transformer.



$$B = \mu H$$

$$\uparrow B = \mu \uparrow H \rightarrow \mu \parallel \text{constant}$$

B (silicon steel) \rightarrow 1.0 to 1.2 Tesla

B (CRGO steel) \rightarrow 1.2 to 1.6 Tesla.

$$\phi = \uparrow B \times A \downarrow$$


If ϕ is constant A will decrease as B is high.

B in CRGO steel B 's more for same H than silicon steel. So for same flux area of core reduces in CRGO steel.

the core having less cross-sectional area with ERGO steel.

INSULATING MATERIALS BETWEEN LAMINATION:-

1. Oxide paint (Red oxide)
2. China clay
3. Japan varnish
4. Thin impregnated paper (i.e. when normal paper immersed in transformer oil it absorbs the insulating oil & become impregnated paper)



1. A_g Gross cross-sectional area of core (i.e. area occupied by magnetic material + area occupied by insulating material)

2. A_n Net cross-sectional area of core (i.e. area occupied by the magnetic material) $\underline{A_n}$

So

$$A_g = L \times b$$

Stacking factor or Iron factor (K_s).

$$= \frac{\text{Net cross-sectional area}}{\text{Gross cross-sectional area}}$$

$$K_s = \frac{A_n}{A_g} \Rightarrow \boxed{A_n = A_g \times K_s}$$

$K_s \approx 0.9$ for practical transformer.

Core staggering :-

The process of bunching the core is called core staggering. Undesirable consequences due to poor core staggering :-

$$\text{Flux} = \frac{\text{MMF}}{S} = \frac{NI_c \uparrow}{S \uparrow}$$

a) If the core laminations are not properly staggered there is a possibility of thin air gap lines between the lamination which increase the reluctance of magnetic path there by demand high excitation current from source.

b) If the laminations are not properly staggered there is possibility of some sound from transformer which is known as magnetic hum.

The main reason for production of magnetic hum in transformer is magnetostriction phenomena.


Magnetostriction:-

This is the tendency of any magnetic material due to which a slight change in dimension of lamination takes place because of alternating nature of flux flowing through it.

In order to reduce noise level in transformer all lamination must be properly staggered.

In steady state flux magnetostriction forces zero.

Alternating flux \rightarrow causes magnetostriction \rightarrow due to which change in dimension of core occur \rightarrow that produces mechanical stress on core \rightarrow which causes vibration of core \rightarrow that finally produces noise. if it is audible range then we can hear noise.



Advantage of cruciform core:-

For same cross sectional area, i.e. $d_1 > d_2$

- * Cruciform core has less diameter of circumference so it requires less amount of insulating material.

- * As dia of inner circle is less the length of turn in cruciform is less therefore this construction reduces amount of copper required for winding.

- * Due to above reasons size, weight & cost of transformer is reduced.



$$\text{Utilization factor of transformer} = \frac{\text{effective c.s. area through which flux passing}}{\text{total c.s. area}}$$

- * As flux distribution in cruciform core is uniform it's utilization factor is more than square core of same c.s. area.

Types of magnetic ckt

1- ϕ Transformer:-

- ① Core type mag ckt
- ② Shell type mag ckt



Horizontal component \rightarrow yoke
Vertical component \rightarrow limb.

Core type

1. Core is ~~short~~ surrounded by winding
2. Mechanical support ^{to windings} is not good
3. No flux division, series ~~winding~~ magnetic ckt
4. Both limbs having same cross sectional area (bcz same flux passing through each limb)
5. Magnetic leakage flux is more
Coefficient of coupling is less.
- ⑥ More copper ^{material} insulation. ^{bcz concentric cylindrical nature of winding}
- ⑦ less insulation.
- ⑧ Economical for high voltage application
- ⑨ Low current application
- ⑩ High voltage & large low kVA rating


Shell type

- ① winding one being surrounded by core
- ② Good mechanical support
- ③ parallel magnetic ckt. flux division.
- ④ Here outer limb having 50% of cross sectional area compared to central limb.
- ⑤ Magnetic leakage flux is less, all flux pass through ^{core} instead of air, because ^{having less air} less reluctance. OR coefficient of coupling is high.
- ⑥ less copper, ^{more} insulation
- ⑦ more insulation
- ⑧ Economical for low voltage application
- ⑨ High current application
- ⑩ low voltage high kVA Rating transformer.


As core type requires less insulation it is suitable for high voltage application.
As core type requires more conductor copper material if it is used for high ct application cost will be more so it is used for low ct application.

Constructional Feature of Transformer winding

Cu or Al material required.


 A solid conductor. A part of total current complete its path within conductor, it is a part of load current so some loss is there called stray load loss.

Instead of solid conductor stranded conductor is used.


 Stranded conductor. All strands are electrically isolated by enamel paint because stray current will not pass to other strand. (This is same process as lamination of core to reduce eddy current) circulating current is less, but load current remain same.

In actual practice T₁ windings are made of stranded conductor instead of solid conductors to reduce stray load loss in winding.


$R_{ac} = 1.6 R_{dc}$. This 1.6 is due to skin effect only.

Skin effect $\propto d^2$, in stranded conductor \times section area \times length of each conductor.

The additional advantage of using stranded conductor instead of solid conductor, it reduces the skin effect of winding.

Placement of wdg in core :-

Cone type transformer :-



Interleaving
The process of keeping half of one winding in one core & another half in other core is called interleaving of winding.


When flux of one winding try to pass through core it links with other winding, so now it not a leakage flux it is a common become a common flux.

Interleaving winding :-

The main purpose of using interleaving nature of winding in core type core is to reduce magnetic leakage flux & hence to improve coefficient of coupling in winding.

Adv of placing L.V winding nearer to the core.

11kV / 3.3kV



case L.V insulation is corresponding to 2.3 kV.

* If HV placed near to core, the insulation required is 11 kV
 ins. winding 7.7 kV
 so total is 18.7 kV whereas in L.V nearer to core is only 11 kV (3.3 + 7.7) ✓

H.V.I of 11 kV - 3.3 kV = 7.7 kV

it is called interwinding insulation & to difference betⁿ HV & LV.


By placing L.V winding nearer to the core the amount of insulation required for transformer can be reduce.

It is also reduces the amount of copper for the winding. [As L.V winding having longer x section area if it placed over HV winding which having shorter x section area. a long length of L.V winding which is required. that means more copper wire.]

Due to above reason the size, weight & cost of transformer will reduce.


If H.V wdg out side the L.V wdg then there is easy access to H.V to provide tapping for voltage control purpose. tapping is used in H.V to get smooth variation & less spark (as current in H.V is less).

Nature of current in wdg w.r.t. position of winding.




H.V wdg flux ϕ_{HV} ϕ_{LV} (It should be in opposite to ϕ_{HV} to satisfy lenz law.)

It is main field flux



For ext-1

If H.V carry current in clockwise direction it's flux is down ward & the flux of secondary should downward to obey lenz's law so it's current direction should be clockwise.





L.V flux ϕ_{HV} main field flux

If the two windings are placed on separate limbs then they should carry current in same direction to satisfy Lenz's law.

If the two windings are placed on same limb then they should carry current in opposite direction to satisfy Lenz's law.

Nature of mechanical force betⁿ L-V & H-V winding.

Lenz's principle.




If the two parallel conductor carry it in same direction then the nature of force betⁿ them is attractive.

If the two parallel conductor carrying current in opposite direction the nature of force betⁿ them is repulsive.



If the windings are placed on same limb they should carry current in opposite direction to satisfy Lenz's law so that nature of force bet the two winding is repulsive.

As amp turns on both side of transformer under normal condition are same the repulsive forces are equal & opposite so that resultant force act on transformer wdg is zero, therefore there is no possibility of dislocation of winding in normal condition.

The conductors within a same winding always experience attractive force because they carry current in same direction.




Radial force are present in cone type core.
Procedure to place winding in shell type core.



Sandwiching nature of winding.
 The main purpose of using sandwiching nature of winding in shell type core is to reduce magnetic leakage flux & hence to improve coefficient of coupling betⁿ winding.

Let HV.W = 3
 LV.W = 3

Here forces are axial.



In shell type construction the extreme L.V winding section should have 50% amp turns in compare to inner L.V winding to get symmetry in order to get the good magnetic balance betⁿ repulsive forces.

In shell extreme winding section should be L.V only to save amount of insulation.

As in cone type transformer winding are concentric, so more length of ~~center~~ winding required. so cu require is more.

But in cone type insulation required is less. In shell type many insulations are required like base insulation (core & windings) & many no of insulation (inter insulation) and one in upper side and lower side of lower & upper L.V winding. In winding there is a force developed in the winding due to the current carrying conductor & (interaction) of the winding between the conductors of winding.

-: Ideal transformer :-


Assumption :-

1. permeability of transformer core is ∞
so no mmf required to produce flux in core
so excitation current is zero. ($I_e = 0$)
2. Iron losses in core is zero.
3. Resistance of transformer winding is zero
i.e. winding made of non-resistive material.
IR drop is zero
I²R loss is zero
4. There is no magnetic leakage flux
i.e. coefficient of coupling is 1
5. Magnetisation curve of transformer core is ~~linear~~ linear.




Non linearity $\frac{I_e}{\phi}$ in practical core.

- ① saturation non linearity
- ② Hysteresis non linearity.



Operation of transformer with finite permeability



As the core having some finite permeability, it requires some amount of current to produce flux in the core. that current is I_m (magnetising current)

I_m = Magnetising component current.

$$I_m = I_m \sin \omega t \quad (\text{As supply is AC})$$

Primary mmf

$$= N_1 I_m$$

$$= N_1 I_m \sin \omega t$$

$$\text{flux} = \frac{\text{MMF}}{R} = \frac{N_1 I_m \sin \omega t}{R} = \phi = \phi_m \sin \omega t$$

So the flux is a time varying flux. So some self & mutual induced emf ^{induced} present in primary & secondary winding respectively. according to Faraday law of electromagnetic induction

Magnitude of self induced emf.

$$e_1 = -N_1 \frac{d\phi}{dt}$$

$$= -N_1 \frac{d}{dt} (\phi_m \sin \omega t)$$

$$= -N_1 \phi_m \omega \cos \omega t$$

$$e_1 = N_1 \phi_m \omega \sin(\omega t - \pi/2)$$

Self induced emf in primary always lag behind the flux quantity exactly by 90° . i.e. after 90° delay emf is produced than flux produced.

$$\text{when } \omega t = \pi$$

$$E_{1\text{max}} = N_1 \phi_m \omega$$

$$E_1 = \frac{E_{1\text{max}}}{\sqrt{2}} = \frac{N_1 \phi_m 2\pi f}{\sqrt{2}}$$

$$E_1 = 4.44 N_1 \phi_m f$$

$$E_1 = 4.44 N_1 B_m A f$$

$$E_1 = 4.44 N_1 B_m A_m f$$

$$A_m = K_c \cdot A_g$$

Magnitude of mutual induced emf.

$$e_2 = -N_2 \frac{d\phi}{dt}$$

$$= -N_2 \frac{d}{dt} (\phi_m \sin \omega t)$$

$$= -N_2 \phi_m \omega \cos \omega t$$

$$e_2 = N_2 \phi_m \omega \sin(\omega t - \pi/2)$$

Mutual induced emf in secondary also lagging behind the flux by 90° and this in phase with the self induced emf in primary.

$$\text{At } \omega t = \pi$$

$$E_{2\text{max}} = N_2 \phi_m \omega$$

$$E_2 = \frac{E_{2\text{max}}}{\sqrt{2}} = \frac{N_2 \phi_m 2\pi f}{\sqrt{2}}$$

$$E_2 = 4.44 N_2 \phi_m f$$


$$E_2 = 4.44 N_2 B_m A_n f$$

These are emf eqⁿ of transformer.

Vector diagram:-



ϕ as reference.
 e_1 & e_2 lags by 90°
 As e_1 produced due to ϕ to e_1 & v_1 should obey lenz's law
 in order to obey lenz's law v_1 should 180° phase difference $\therefore e_1$ as shown in fig. vector diagram.



Observations of emf eqⁿ:

$$\frac{E_1}{N_1} = \frac{444 B_m A_m N_1 f}{4.71 B_m A_m N_1 f} \quad [\text{emf / turn in primary}]$$

$$\frac{E_2}{N_2} = 4.71 B_m A_m f \quad [\text{see emf / turn in sec}]$$

∴ Emf per turn per second on both side of transformer is same

$$\frac{E_1}{N_1} = \frac{E_2}{N_2}$$

$$\frac{E_2}{E_1} = \frac{N_2}{N_1} = k \quad [\text{transformation ratio of transformer}]$$

Voltage rating of transformer (written on transformer name plate) are induced voltage (i.e. E_1 & E_2)

Turn ratio:

$$\frac{N_1}{N_2} = \frac{E_1}{E_2} = \frac{1}{k}$$

During operation of tran. As during operation we can change $\frac{V_1}{f}$ or $\frac{V_2}{f}$

$$B_m \propto \frac{E_1}{f} \propto \frac{V_1}{f} \quad \text{as } E_1 \propto V_1$$

If we want to maintain B_m as constant

∴ we have to keep $\frac{V_1}{f}$ constant.

$$\Rightarrow \frac{V_{11}}{f_1} = \frac{V_{12}}{f_2} \quad \text{so } B_m \text{ is constant}$$

200V, 50 Hz

160V, $f = ?$


so that B_m is constant.

$$\text{so } \frac{V_{11}}{f_1} = \frac{V_{12}}{f_2}$$

$$\Rightarrow \frac{200}{50} = \frac{160}{f_2} \quad \text{so } f_2 = 40 \text{ Hz}$$

As in tran flux is constant i.e. $\frac{V}{f}$ is constant.

* Supply Voltage to frequency ratio should be constant.



V is constant &
 If f is reduced B_m is increased, so for this high B_m , a high value of magnetising current is required.

If it is required to reduce the frequency for any application so same time reduce the supply voltage.

* By keeping applied voltage constant if the frequency of trans operation of transformer decreases then B_m of trans increases which drives the transformer into deep saturation thereby demands very high magnetising component of current from source.

That's why never reduce only frequency by keeping supply voltage constant.

If it is necessary to operate the transformer at reduced voltage frequency, applied voltage should be reduced simultaneously to maintain V/f constant.

Rating of Transformer :-

$\downarrow E_1 \propto f \downarrow$ $E_1 I_1$ - Apparent power.
 The kVA rating of transformer changes proportionally with ^{change in} frequency.

100 kVA, US made 60 Hz

100 \times $(\frac{50}{60})$ India, 50 Hz

Some times will be ^{having} 88 kVA in india operating frequency.

During design of transformer :-

which having loss on size, weight, cost.

① 100 kVA, 25 Hz

② 100 kVA, 50 Hz

③ 100 kVA, 75 Hz


④ 100 kVA, 100 Hz

kVA is fixed = $E_1 I_1$

As I_1 depends on size of conductor & $E_1 = 4.44 f N \phi_m$

In design we can change A & N

2nd assumption :- i.e iron loss is absent but in practically two losses are there, so now will consider, operation of transformer with iron loss :->



As iron loss present in core so supply has to give a current for this loss (I_w)

I_w = iron loss component of current.
 ∴ it's function is to supply iron losses present in core.

$\vec{I}_0 = \vec{I}_m + \vec{I}_w$ - In no load condition.

I_m
 Reactive Component current
 watt less current
 It is quadrature with V_1

I_w
 Active comp of current
 Wattful component of current
 Active component in phase with V_1

$I_m \gg I_w$
 4 to 6% of full load current 1 to 2% of full load current.

Normally $I_0 \Rightarrow$ 5 to 8% of full load current.


To represent the behaviour of I_m we use X_0 it is fictitious inductor.

As I_w & V are same phase like resistor so I_w behaviour represent by a resistance parameter.
~~resist~~

~~vector~~
 As this is only to produce flux in core, not related to the active power, it is called Reactive component or wattless component. And we know reactive component lag voltage, be an. this is the property of inductor

We know active component is in phase with voltage this is the property of resistance & we represent in a resistor.

Vector diagram:-



$\phi_0 \rightarrow 70 \text{ to } 75^\circ$
 $\cos \phi_0 = \text{NL p.f. of transformer}$
 $\approx 0.2 \text{ lag}$

The transformer has poor no load p.f. order of 0.2 lagging because it's $I_m \gg I_w$ current because of this relation p.f. is poor.

By keeping applied voltage constant if the frequency of operation reduce consequences are

- ① Magnetising component drawn by primary winding increases. (As B_m increases)
- ② As I_m increases no load p.f. of tran decreases further.

$I_0 \angle -\phi$

$I_{m \text{ or } I_w} = I_0 \sin \phi_0$

$I_w = I_0 \cos \phi_0$

No load power = $V_1 I_0 \cos \phi_0$

= $V_1 I_w$

= Iron losses


(It is approximate only)

~~So total power loss in~~

So total power in no load condition is the only Iron loss.

The power consumed by tran under no load condition is approximately equal to iron losses in transformer only (if the primary winding resistance is considered small amount of $I^2 R$ loss in primary take place in addition to iron loss under no load condition).

Equivalent ckt of transformer under no load.




Shunt branch or NL branch of equivalent ckt of transformer.

As I_0 is only flux through the primary winding, hence reflect on secondary side. It's component I_w & I_m behavior should be connected to primary only. So R_0 & X_0 are connected in parallel to primary winding.

As it bypass some current of primary winding, they are connected in parallel.

operation of transformer under load condition:



$N_1 \cdot I_{m1} = \text{primary m.m.f}$


$\phi = \text{primary flux or Mainfield flux or working load.}$

$V_2 = \text{secondary terminal voltage.}$

$I_2 = \text{secondary load current.}$

direction of I_2 can be found out by lenz's law.

So this I_2 will produce $N_2 I_2$ mmf



$N_2 I_2$ mmf secondary flux mmf
 $\phi_2 = \text{secondary flux}$


So this flux should oppose the main field flux, to satisfy the lenz law of production of effect i.e. I_2 . angle betⁿ ϕ_1 & ϕ_2 is 180° .

I_1' = load component of ~~load~~ primary current.

$$N_1 V_1 = 220 \quad e_1 = 210$$

As 10 v drive no load current in transformer.

due to this ~~at~~ additional current I_1' in primary, it produces some mmf = $N_1 I_1'$ which in turn produce ϕ_1' which ~~is~~ ~~not~~ ~~known~~ as load component of primary flux.



for power transformer ϕ_1' should nullify the effect of ϕ_2 so flux in core is ϕ always ϕ . So net flux component of load is zero.

The flux in core always maintain constant irrespective of magnitude of load across it's secondary terminals. That's why the transformer can be treated as constant flux device.

$$\text{Under steady state condition} = \phi_1' = \phi_2$$

If the load increase the ϕ_2 increase so I_1' in primary increases so that ϕ_1' increases so ϕ_1' will be again ~~equal~~ to ϕ_2 . So again steady state condition will be achieve. As automatically these process takes place it is called a control device.

$$\phi_1' = \phi_2$$

$$N_1 I_1' = N_2 I_2$$

Load component of primary amp turn = Sec A.T
as I_0 ~~not~~ transfer from primary to secondary.

So we can say primary mmf = sec mmf. as $I_1 = I_0 + I_1'$

$$\frac{E_2}{E_1} = \frac{N_2}{N_1} = \frac{I_1'}{I_2} = k$$

transformation ratio as I_0 not constant. SO exact value of $k = \frac{I_1'}{I_2}$

$$I_1' = k I_2$$


$$E_1 I_1' = E_2 I_2$$

Load component of primary kVA = sec kVA

If I_0 neglected \Rightarrow

<p>These are approximate the value of the value</p>	}	$I_1 \approx I_1'$	}	exact P.A.C
		$N_1 I_1 = N_2 I_2$		$N_1 I_1' = N_2 I_2$
		$k \approx \frac{I_1}{I_2}$		like that
		$E_1 I_1 \approx E_2 I_2$		

Vector diagram :-



lagging load p.f

The phase of I_2 with V_2 depends on the nature of load
 ϕ_2 is called load p.f angle.
 • Secondary p.f.

$$\phi_0 = \angle V_1 \times I_0$$

$$\phi_2 = \angle V_2 \times I_2$$

$$\phi_1 = \angle V_1 \times I_1$$

$$\cos \phi_0 = \text{N.L. p.f.}$$

$$\cos \phi_2 = \text{Sec p.f.} = \text{load p.f.}$$

$$\cos \phi_1 = \text{primary p.f.}$$

Sec p.f. is given or this is known power factor.

$$\cos \phi_1 \neq \cos \phi_2$$


But if I_0 is neglected.

$I_1' = KI_2$ then only $\phi_1 \approx \phi_2$ then $\cos \phi_1 = \cos \phi_2$

$$\boxed{\cos \phi_1 \approx \cos \phi_2 \approx \text{load p.f.}}$$

3rd assumption :-

Effect of winding resistance on the operation of transformer.



two undesirable consequence.

- ① $I R$ drop
- ② $I^2 R$ loss.

when R is consider V_1 should have two component
i.e. E_1 & drop.

$$\vec{V}_1 = -E_1 + I_1 R_1$$

$$\vec{E}_2 = \vec{V}_2 + I_2 R_2$$


Total copper loss in transformer = $I_1^2 R_1 + I_2^2 R_2$

It is always convenient to consider all resistance in one side for easy analysis.

we can not transfer as our wish. So condition is copper loss in that resistance

Condition that must satisfied ~~for~~ when transferring the winding resistance from one side to other side copper loss in that resistance should maintain constant

Cu loss in R before $T_2 =$ Cu loss in same R after T_2



Sec to primary transfer

$$I_2^2 R_2 = I_1^2 R_2'$$

$$\Rightarrow R_2' = R_2 \left(\frac{I_2}{I_1} \right)^2$$

$$R_2' = \frac{R_2}{k^2}$$

R_2' = equivalent resistance of secondary referred to primary side.

Primary to secondary side :-

$$I_1^2 R_1 = I_2^2 R_1'$$

$$R_1' = k^2 R_1$$

R_1' = equivalent resistance of primary referred to sec side.

$$R_{01} = R_1 + R_2' = R_1 + R_2/k^2$$

$$R_{02} = R_2 + R_1' = R_2 + k^2 R_1$$

$$\begin{aligned} \text{So total cu loss} &= I_1^2 R_{01} \\ &= I_2^2 R_{02} \end{aligned}$$

→ equivalent resistance of transformer referred to secondary side.

drop in resistance expressed in % of supply voltage is known as per unit resistance.

P.U primary ~~resistive~~ drop = $\frac{I_1 R_1}{E_1}$

per unit sec ~~resistive~~ drop = $\frac{I_2 R_2}{E_2}$

Total per unit resistive drop with primary = $\frac{I_1 R_1}{E_1}$

" " " " " " " " sec side = $\frac{I_2 R_2}{E_2}$

Per unit value of resistive drop on both side of transformer is same

percentage ~~drop~~ ^{value} of resistive drop on both side of trans is same. percentage = per unit $\times 100$

percentage drop =


In p.u system the p.u resistive drop is also simply known as p.u resistance of transformer.

Q. A

As p.u resistance on both side of transformer is same it is easy to transfer p.u value of resistance from one side to another side when compared to resistance in ohmic value where $\times k^2$ or $\frac{1}{k^2}$ is required.

4th assumption:-

Operation of transformer with magnetic leakage flux:



leakage flux is due to local component of flux.


leakage flux depends on load it is not a constant. But flux is more always ϕ i.e. due to no load current.

ϕ_{L1} is in phase with I_1


ϕ_{L2} is in phase with I_2

Magnetic leakage flux is the part of the load component of flux which links either HV or LV winding but not both and it is not having any role in transferring power from one ckt to another. If the leakage flux in transformer is more the magnitude of power transfer from one ckt to other ckt decreases, that's why the leakage flux should be as minimum as possible during operation of transformer.

Magnetic flux in transformer depends on magnitude of load current in the windings. That's why mag leakage flux is not constant in transformer core it is treated as variable flux. Magnetic leakage flux available in primary and secondary winding are in phase with respective load current.



When ever magnetic flux (leakage) are available at primary and secondary some additional emf will be induced in both primary and secondary due to leakage flux and these emfs are lagging behind the respective load current exactly by 90° .




Here E_{L1} leads I_1 by 90° that is the behaviour of induction so this drop is represented as drop in an inductor.

E'_{22} is 180° phase shift to E_{12} coz E'_{12} is the extra component of supply voltage to compensate to supply the voltage drop due to leakage flux. Which lead I_2 by 90° . So which is a property of inductor, so this voltage drop is represented by an inductor.

$$X_2 = \frac{E'_{12}}{I_2}$$

$$X_1 = \frac{E_{21}}{I_1}$$



To take the account of emf due to magnetic leakage flux some fictitious or imaginary reactance assumed in series with primary and secondary winding such that the magnitude of voltage drop across the reactance is used to represent emf in the windings due to magnetic leakage flux. These imaginary reactances in transformer are called leakage reactance.

$$\bar{V}_1 = -\bar{E}_1 + jI_1 X_1$$

$$V_1 = -E_1 + I_1 R_1 + jI_1 X_1$$

$$= -E_1 + I_1 (R_1 + jX_1)$$

$$V_1 = -E_1 + I_1 Z_1$$

Z_1 is primary leakage impedance, as it is a function of leakage reactance.

$$E_2 = V_2 + jI_2 X_2$$

$$E_2 = V_2 + I_2 R_2 + jI_2 X_2$$

$$= V_2 + I_2 (R_2 + jX_2)$$

$$E_2 = V_2 + I_2 Z_2$$

Z_2 = secondary leakage reactance impedance

→ Exact voltage equation of transformer.

* The condition that must be satisfied while transferring leakage reactance is per unit value of reactance drop should be maintain constant.

$$\text{P.u primary reactance drop} = \frac{I_1 X_1}{E_1}$$

$$\text{P.u secondary reactance drop} = \frac{I_2 X_2}{E_2}$$

P.u reactance drop before transfer = P.u reactance drop after transfer.

R

Transfer of reactance from sec to primary:-

$$\frac{I_2 X_2}{E_2} = \frac{I_1' X_2'}{E_1}$$

$$\Rightarrow X_2' = X_2 \times \frac{E_1}{E_2} \times \frac{I_2}{I_1} \Rightarrow \boxed{\frac{X_2}{K^2} = X_2'}$$

Primary to secondary:-

$$\frac{I_1 X_1}{E_1} = \frac{I_2 X_1'}{E_2} \Rightarrow \boxed{X_1' = K^2 X_1}$$

Total reactance when refer to primary side

$$= X_1 + X_2' = \boxed{X_1 + X_2/K^2}$$

When refer to (X₀₂) secondary i.e. X₀₂ = X₂ + X_{1'} = $\boxed{X_2 + X_1 K^2}$

Total p.u reactance drop w.r.t primary-


$$= \boxed{\frac{I_1 X_{02}}{E_1} = \text{p.u reactance w.r.t primary.}}$$

Total p.u reactance drop w.r.t secondary-

$$= \boxed{\frac{I_2 X_{02}}{E_2} = \text{p.u reactance w.r.t secondary.}}$$


The p.u reactance drop on both side of transformer is same
As pu reactance on both side of transformer is same it's
easy to transfer the pu value of reactance from one side
to another side when compared to reactance in ohmic value.

Exact equivalent ckt diagram of transformer:-




No load current will flow only in primary it will not reflect on secondary side. cannot transfer to sec. so it is connected in parallel with primary winding.

Equivalent ckt when refer to primary:



1st approximation to equivalent ckt



Deviation in above equivalent ckt:

1. No load primary impedance drop is neglected i.e. $I_0 Z_1$
2. No load primary cu loss is also neglected = $I_0^2 R_1^2$, on under estimated.
3. As $|V_1| > |E_1|$
No load current & it's components are over estimated as connected across high voltage $|V_1|$
so No load current I_0 increases, hence I_w & I_m are also increases
4. so I non loss over compare estimated.

∴ Under estimated no load cu loss = Over estimated iron loss.

2nd approximation to Equivalent ckt of Transformer:

By neglecting no load current as it's very less.

